

high-pressure graphitization

A term which refers to the solid-state transformation of *non-graphitic carbon* into *graphite* by heat treatment under elevated pressure (e.g. 100 to 1000 MPa) so that a definitely higher degree of *graphitization* is achieved at lower temperature and/or for a shorter heat treatment time than in heat treatment of the same non-graphitic material at atmospheric pressure.

1995, 67, 495