

primary crystallization

The first stage of *crystallization*, considered to be ended when most of the spherulite surfaces impinge on each other. In isothermal crystallization, primary crystallization is often described by the *Avrami equation*.

P.B. 85