

puffing

An irreversible expansion of some *carbon artifacts* during *graphitization heat treatment* between 1650 and 2700 K.

Notes:

Puffing is caused by the release of heteroatoms, for instance sulfur atoms, from the *coke* in association with specific microstructural rearrangements.

1995, 67, 502