

### **X-ray spectroscopy**

X-ray spectroscopy consists of three steps: (a) excitation to produce emission lines characteristic of the elements in the material, (b) measurement of their intensity, and (c) conversion of *X-ray intensity* to concentration by a calibration procedure which may include correction for *matrix effects*.

1980, 52, 2544