

crowding (in solvent extraction)

The displacement of an impurity from an extract phase by contact with a solution containing the main extractable solute. The main solute need not be present in a pure solution but should have a higher distribution ratio than the impurities present.

See also *scrubbing*, *exchange extraction*.
1993, 65, 2386